Bengalla Mining Company Pty. Limited
Bengalla Road, (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia
A.B.N. 32 053 909 470

Bengalla Mine

State Significant Development 5170
Monthly Monitoring Data Summary

October 2018

Bengalla Mining Company Pty. Limited
Bengalla Road, (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia
A.B.N. 32 053 909 470

CONTENTS

TABLES

Bengalla Mining Company Pty. Limited
Bengalla Road, (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia
A.B.N. 32 053 909 470

1. INTRODUCTION

State Significant Development (SSD) 5170 requires the Bengalla Mining Company Pty Ltd (BMC) to make a comprehensive summary of the Bengalla Mine (Bengalla) monitoring results, reported in accordance with the specifications in any conditions of SSD-5170, or any approved plans and programs, publicly available on its website. This document has been prepared in accordance with the Department of Planning and Environment (DPE) *Web-Based Reporting Guideline* (October 2015) to satisfy the above requirement.

This document provides a summary of environmental monitoring data sampled as prescribed by SSD-5170 for October 2018 (Reporting Period). Monitoring data provided is as follows:

- Air quality, particulate matter less than 10 microns (PM_{10}), total suspended particulate (TSP) matter and depositional dust;
- Noise; and
- Blast overpressure and ground vibration.

Monitoring Data Obtained: 16 November 2018

Monitoring Data Published: 8 January 2019

2. AIR QUALITY

The air quality monitoring program at Bengalla is undertaken in accordance with the requirements of SSD-5170 (as modified), EPL 6538 and the Bengalla Air Quality Management Plan (AQMP). Air quality monitoring results relevant to SSD-5170 are summarised in the following sections.

2.1 Particulate Matter less than 10 Microns

To evaluate the performance of Bengalla against the SSD-5170 criterion for particulate matter, BMC operates and maintains three High Volume Air Samplers (HVAS) measuring PM_{10}. Additional PM_{10} data is sourced from Mt Arthur Coal through an information sharing agreement. The HVAS are run for 24 hours every six days.

PM_{10} data for the Reporting Period is provided in **Table 1**.

Pollutant: PM_{10}

Unit of measure: Micrograms per cubic metre (µg/m3)

Monitoring location: See **Table 1** and **Appendix A.**

Monitoring frequency: 24 hours every 6 days

24 Hour Average Criteria: 50 µg/m3

Annual Average Criteria: 90 µg/m3

Sampled: 04/10/2018 – 28/10/2018

Table 1. PM_{10} Monitoring Summary

Run Date	Run Date Reading (µg/m3)			
	PM10-1 Racecourse Road	PM10-2 St James School	PM10-3* Roxburgh Road	PM10-4 Wybong Road
04/10/2018	26	24	<1	32
10/10/2018	15	16	25	22
16/10/2018	22	36	23	33
22/10/2018	30	27	13	45
28/10/2018	36	24	32	40

* Data sourced from Mt Arthur Coal

For the Reporting Period, no elevated 24-hour average PM_{10} readings were recorded.

Bengalla Mining Company Pty. Limited
Bengalla Road, (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia
A.B.N. 32 053 909 470

2.2 Total Suspended Particle Matter

To evaluate the performance of Bengalla against the SSD-5170 criterion for particulate matter, BMC operates and maintains five HVAS measuring TSP. The HVAS are run for 24 hours every six days.

TSP data for the Reporting Period is provided in **Table 2**.

Pollutant: TSP

Unit of measure: µg/m3

Monitoring location: See **Table 2** and **Appendix B.**

Monitoring frequency: 24 hours every 6 days

Annual Average Criteria: 90 µg/m3

Sampled: 04/10/2018 – 28/10/2018

Table 2. TSP Monitoring Summary

Run Date	Run Date Reading (µg/m3)				
	HV01 Wybong Road (East)	HV02 Racecourse Road	HV03 Logues Lane	HV04 St James School	HV06 Wybong Road (West)
04/10/2018	64	71	61	57	105
10/10/2018	32	43	32	32	70
16/10/2018	60	53	38	143	42
22/10/2018	69	79	59	67	160
28/10/2018	74	84	65	58	129

2.3 Depositional Dust

To evaluate the performance of Bengalla against the SSD-5170 criterion for depositional dust, BMC operates and maintains 14 depositional dust gauges surrounding the Bengalla operations.

Depositional dust data for the Reporting Period is provided in **Table 3**.

Pollutant:	Depositional Dust
Unit of measure:	Grams per metre squared per month (g/m^2/month)
Monitoring location:	See **Table 3** and **Appendix C.**
Monitoring frequency:	Monthly
Maximum depositional dust increase criteria:	2 g/m^2/month
Maximum total depositional dust criteria:	4 g/m^2/month
Sampled:	18/09/2018 – 16/10/2018

Bengalla Mining Company Pty. Limited
Bengalla Road, (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia
A.B.N. 32 053 909 470

Table 3. Depositional Dust Monitoring Summary

Sampling point		Measured Value	Sampling Comments
D01	Queen Street, Muswellbrook	1.0	Insects
D02	King Street, Muswellbrook	2.1	Insects, bird droppings
D04A	Industrial Estate, Muswellbrook	2.5	Insects
D05	Intersection Kayuga and Wybong Road, Muswellbrook	1.6	Insects
D06	Logues Lane, Muswellbrook	4.1	Insects
D07A	St James School, Muswellbrook	1.3	Insects
D08	Denman Road, Muswellbrook	1.5	Insects
D09	Wybong Road, Muswellbrook	2.1	Insects
D10	Racecourse Road, Muswellbrook	2.1	Insects
D20	Wyndams Arms R.O.W., Muswellbrook	5.4	Insects
D23B	Logues Lane, Muswellbrook	1.2	Insects
D25	Roxburgh Road, Muswellbrook	3.6	Insects
D26	Wybong Road, Muswellbrook	2.7	Insects
DA	Roxburgh Road, Muswellbrook	3.3	Insects

Bengalla Mining Company Pty. Limited
Bengalla Road, (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia
A.B.N. 32 053 909 470

3. NOISE

The noise monitoring program at Bengalla is undertaken in accordance with the requirements of SSD-5170 (as modified), EPL 6538 and the Bengalla Noise Management Plan (NMP).

BMC undertakes compliance attended noise monitoring for 15 minutes once per calendar month during the night period (10 pm to 7 am) at three locations representative of the nearest private receivers.

Noise monitoring data for the Reporting Period is provided in **Table 4**.

Pollutant:	Noise – Bengalla Only
Unit of measure:	L_{Aeq} (15 minute)
Monitoring location:	See **Table 4** and **Appendix D.**
Monitoring frequency:	Monthly
AN01 criteria:	35 dB(A)
AN04 criteria:	35 dB(A)
AN03 criteria:	40 dB(A)
Sampled:	28-29 October 2018

Table 4. Noise – Bengalla Only[1] LAeq (15 minute) Monitoring Summary

Sampling point		Sample Date	Sample Time	Measured value
AN01	1431 Wybong Road	28/09/18	23:14	29
AN03	1312 Denman Road	29/09/18	00:02	IA
AN04	Opposite 9 Racecourse Road	29/09/18	00:07	IA

1.LAeq,15minute operational noise levels for Bengalla in the absence of all other noise sources.

IA - Inaudible. When there was no noise from the source of interest (Bengalla Mine) audible at the monitoring location.

For the Reporting Period noise data were below the SSD-5170 criteria.

Bengalla Mining Company Pty. Limited
Bengalla Road, (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia
A.B.N. 32 053 909 470

4. BLASTING

BMC maintains three blast monitors to measure blast overpressure and ground vibration against the SSD-5170 criteria.

The blast overpressure and ground vibration data for the Reporting Period is provided in **Table 5**.

Pollutant:	Air blast overpressure & ground vibration peak particle velocity
Unit of measure:	dB (Lin Peak) and millimetres per second (**mm/s**)
Monitoring locations:	See **Tables 5** and **Appendix D.**
Monitoring frequency:	All blasts
Overpressure criteria:	a) 115 linear decibels (**dB(L)**) for more than 5% of the total number of blasts carried out on the premises within the 12 months annual reporting period; and b) 120 dB(L) at any time.
Ground vibration criteria:	a) exceed 5 millimetres/second (**mm/s**) for more than 5% of the total number of blasts carried out on the premises within the 12 months annual reporting period; and b) 10mm/s at any time.
Sampled:	01/10/2018 – 31/10/2018

Bengalla Mining Company Pty. Limited
Bengalla Road, (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia
A.B.N. 32 053 909 470

Table 5. Blast Overpressure Monitoring Summary

Date	Time of Blast	Ground Vibration (mm/s)			Overpressure (dBL)		
		BLK	MRE	SCH	BLK	MRE	SCH
03/10/18	2:57:23 PM	0.18	0.86	0.06	94.00	95.90	95.20
03/10/18	2:58:40 PM	0.22	1.94	0.08	93.80	102.90	94.40
05/10/18	2:59:09 PM	0.13	0.21	0.04	91.40	95.10	104.40
09/10/18	2:55:09 PM	0.43	3.08	0.14	91.50	94.80	94.00
11/10/18	4:24:07 PM	0.12	0.77	0.05	113.20	111.30	103.40
12/10/18	3:51:45 PM	0.09	0.47	0.05	100.00	109.40	95.90
15/10/18	11:16:26 AM	0.27	1.73	0.12	112.60	115.70	88.40
16/10/18	1:41:36 PM	0.05	0.34	0.04	104.60	104.90	92.80
16/10/18	4:08:15 PM	0.52	2.93	0.16	112.90	109.40	101.70
19/10/18	3:49:47 PM	0.38	2.35	0.17	92.70	94.90	91.40
20/10/18	2:54:04 PM	0.05	0.28	0.04	100.50	105.40	98.20
24/10/18	11:23:12 AM	0.11	0.89	0.08	108.60	106.00	100.90
25/10/18	2:54:26 PM	0.17	0.98	0.16	95.40	102.30	91.20
26/10/18	2:56:07 PM	0.03	0.08	0.01	81.80	91.00	88.50
27/10/18	11:23:30 AM	0.10	0.35	0.06	94.40	97.00	94.70
29/10/18	4:21:50 PM	0.08	0.68	0.03	115.10	111.60	95.80
31/10/18	11:00:11 AM	0.08	0.55	0.05	85.70	98.20	89.70

For the Reporting Period, overpressure and ground vibration data were below the maximum criteria and within the 5% allowance limit.

Appendix A

PM10 Monitoring Locations

PRJ31060_BengallaMineNSW_50cm_19102017 _gda94mga56_ortho_full-area

BENGALLA

BENGALLA MINE

PM10 Monitoring Locations

Appendix B

TSP Monitoring Locations

PRJ31060_BengallaMineNSW_50cm_19102017 _gda94mga56_ortho_full-area

BENGALLA

BENGALLA MINE

TSP Monitoring Locations

Appendix C

Depositional Dust Monitoring Locations



PRJ31060_BengallaMineNSW_50cm_19102017 _gda94mga56_ortho_full-area

BENGALLA

BENGALLA MINE

Depositional Dust Monitoring Locations

Appendix D

Noise and Blast Monitoring Locations



HB BENGALLA EPL 1428 F1 Bengalla Compliance Acoustic Monitoring Network - Aerial Version 09 09 2016

BENGALLA MINE

Bengalla Compliance Acoustic Monitoring Network

FIGURE 1