



Bengalla Mining Company Pty Limited

Bengalla Road (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia

T: +61 2 6542 9500
F: +61 2 6542 9599

ABN 32 053 909 470

bengalla.com.au

Bengalla Mine

State Significant Development 5170 Monthly Monitoring Data Summary

September 2022



Bengalla Mining Company Pty Limited

Bengalla Road (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia

T: +61 2 6542 9500
F: +61 2 6542 9599

ABN 32 053 909 470

bengalla.com.au

CONTENTS

1. INTRODUCTION.....	3
2. AIR QUALITY	4
3. NOISE.....	7
4. BLASTING.....	8

TABLES

Table 1. PM ₁₀ Monitoring Summary	4
Table 2. TSP Monitoring Summary	5
Table 3. Depositional Dust Monitoring Summary.....	6
Table 4. Noise – Bengalla Only ¹ LAeq (15 minute) Monitoring Summary	7
Table 5. Blast Overpressure Monitoring Summary	9



Bengalla Mining Company Pty Limited

Bengalla Road (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia

T: +61 2 6542 9500
F: +61 2 6542 9599

ABN 32 053 909 470

bengalla.com.au

1. INTRODUCTION

State Significant Development (SSD) 5170 (as modified) requires the Bengalla Mining Company Pty Ltd (BMC) to make a comprehensive summary of the Bengalla Mine (Bengalla) monitoring results, reported in accordance with the specifications in any conditions of SSD-5170 (as modified), or any approved plans and programs, publicly available on its website. This document has been prepared in accordance with the Department of Planning and Environment (DPE) *Web-Based Reporting Guideline* (October 2015) to satisfy the above requirement.

This document provides a summary of environmental monitoring data sampled as prescribed by SSD-5170 (as modified) for September 2022 (Reporting Period). Monitoring data provided is as follows:

- Air quality, particulate matter less than 10 microns (PM₁₀), total suspended particulate (TSP) matter and depositional dust;
- Noise; and
- Blast overpressure and ground vibration.

2. AIR QUALITY

The air quality monitoring program at Bengalla is undertaken in accordance with the requirements of SSD-5170 (as modified), EPL 6538 and the Bengalla Air Quality Management Plan (AQMP). Air quality monitoring results relevant to SSD-5170 are summarised in the following sections.

2.1 Particulate Matter less than 10 Microns

To evaluate the performance of Bengalla against the SSD-5170 criterion for particulate matter, BMC operates and maintains four High Volume Air Samplers (HVAS) measuring PM₁₀. The HVAS are run for 24 hours every six days.

PM₁₀ data for the Reporting Period is provided in **Table 1**.

Pollutant:	PM ₁₀
Unit of measure:	Micrograms per cubic metre (µg/m ³)
Monitoring location:	See Table 1 and Appendix A .
Monitoring frequency:	24 hours every 6 days
24 Hour Average Criteria:	50 µg/m ³
Annual Average Criteria:	25 µg/m ³
Sampled:	01/09/2022 – 30/09/2022

Table 1. PM₁₀ Monitoring Summary

Run Date	Run Date Reading (µg/m ³)			
	PM10-1 Racecourse Road	PM10-2 St James School	PM10-3 Roxburgh Road	PM10-4 Wybong Road
01/09/2022	22.3	16.0	29.5	28.0
07/09/2022	13.6	14.1	20.2	35.0
13/09/2022	12.7	11.3	9.8	56.1
19/09/2022	19.2	15.6	3.6	3.6
25/09/2022	8.5	3.1	4.4	6.6

(Table 1 represents total impact (ie incremental increase in concentration due to the development plus background concentrations due to other sources))

2.2 Total Suspended Particle Matter

To evaluate the performance of Bengalla against the SSD-5170 criterion for particulate matter, BMC operates and maintains five HVAS measuring TSP. The HVAS are run for 24 hours every six days.

TSP data for the Reporting Period is provided in **Table 2**.

Pollutant:	TSP
Unit of measure:	µg/m ³
Monitoring location:	See Table 2 and Appendix B .
Monitoring frequency:	24 hours every 6 days
Annual Average Criteria:	90 µg/m ³
Sampled:	01/09/2022 – 30/09/2022

Table 2. TSP Monitoring Summary

Run Date	Run Date Reading (µg/m ³)				
	HV01 Wybong Road (East)	HV02 Racecourse Road	HV03 Logues Lane	HV04 St James School	HV06 Wybong Road (West)
01/09/2022	37.9	48.7	28.8	32.4	96.0
07/09/2022	23.6	110	24.0	29.4	136
13/09/2022	48.9	52.4	35.5	38.2	166
19/09/2022	97.1	86.1	52.9	66.5	21.2
25/09/2022	41.0	56.8	24.1	34.1	27.2

(Table 2 represents total impact (ie incremental increase in concentration due to the development plus background concentrations due to other sources))

2.3 Depositional Dust

To evaluate the performance of Bengalla against the SSD-5170 criterion for depositional dust, BMC operates and maintains 14 depositional dust gauges surrounding the Bengalla operations.

Depositional dust data for the Reporting Period is provided in **Table 3**.

Pollutant:	Depositional Dust
Unit of measure:	Grams per metre squared per month (g/m ² /month)
Monitoring location:	See Table 3 and Appendix C .
Monitoring frequency:	Monthly
Maximum depositional dust increase criteria:	2 g/m ² /month ^(b)
Maximum total depositional dust criteria:	4 g/m ² /month ^(a)
Sampled:	18/8/2022 – 15/9/2022

(a) Total impact (ie incremental increase in concentrations due to the development plus background concentrations due to other sources);

(b) Incremental impact (ie incremental increase in concentration due to the development on its own)

Table 3. Depositional Dust Monitoring Summary

Sampling point		Measured Value (September 2022) g/m ² /month	Sampling Comments
D01	Queen Street, Muswellbrook	0.5	Insects
D02	King Street, Muswellbrook	0.8	Insects
D04A	Industrial Estate, Muswellbrook	1.6	Insects, vegetation and bird droppings
D05	Intersection Kayuga and Wybong Road, Muswellbrook	2.2	Insects
D06	Logues Lane, Muswellbrook	1.4	Insects
D07A	St James School, Muswellbrook	1.0	Insects
D08	Denman Road, Muswellbrook	0.9	Insects
D09	Wybong Road, Muswellbrook	2.2	Insects
D10	Racecourse Road, Muswellbrook	1.4	Insects
D20	Wyndams Arms R.O.W., Muswellbrook	3.1	Insects
D23B	Logues Lane, Muswellbrook	1.2	Insects
D25	Roxburgh Road, Muswellbrook	2.4	Insects
D26	Wybong Road, Muswellbrook	1.4	Insects
DA	Roxburgh Road, Muswellbrook	2.2	Insects, vegetation

Operator, for and on behalf of Bengalla Joint Venture, an unincorporated joint venture between:
New Hope Bengalla Pty Ltd, Taipower Bengalla Pty Limited.

(Table 3 represents total impact (ie incremental increase in concentration due to the development plus background concentrations due to other sources))

3. NOISE

The noise monitoring program at Bengalla is undertaken in accordance with the requirements of SSD-5170 (as modified), EPL 6538 and the Bengalla Noise Management Plan (NMP).

Compliance attended noise monitoring is undertaken for 15 minutes once per calendar month during the night period (10 pm to 7 am) at three locations representative of the nearest private receivers.

Noise monitoring data for the Reporting Period is provided in **Table 4**.

Pollutant:	Noise – Bengalla Only
Unit of measure:	L _{Aeq} (15 minute)
Monitoring location:	See Table 4 and Appendix D .
Monitoring frequency:	Monthly
AN01 criteria:	35 dB(A)
AN04 criteria:	35 dB(A)
AN03 criteria:	40 dB(A)
Sampled:	26 - 27 September 2022

Table 4. Noise – Bengalla Only¹ LAeq (15 minute) Monitoring Summary

	Sampling point	Sample Date	Sample Time	Measured value
AN01	1431 Wybong Road	26/9/2022	23:04 – 23:19	34
AN03	1312 Denman Road	26/9/2022	23:42 – 23:57	IA
AN04	Opposite 9 Racecourse Road	27/9/2022	00:24 – 00:39	IA

IA - Inaudible. When there was no noise from the source of interest (Bengalla Mine) audible at the monitoring location.

1. LAeq,15minute operational noise levels for Bengalla in the absence of all other noise sources.



Bengalla Mining Company Pty Limited

Bengalla Road (Locked Mailbag 5)
Muswellbrook NSW 2333 Australia

T: +61 2 6542 9500

F: +61 2 6542 9599

ABN 32 053 909 470

bengalla.com.au

4. BLASTING

BMC maintains three blast monitors to measure blast overpressure and ground vibration against the SSD-5170 criteria.

The blast overpressure and ground vibration data for the Reporting Period is provided in **Table 5**.

Pollutant:	Air blast overpressure & ground vibration peak particle velocity
Unit of measure:	dB (Lin Peak) and millimetres per second (mm/s)
Monitoring locations:	See Tables 5 and Appendix D .
Monitoring frequency:	All blasts
Overpressure criteria:	a) 115 linear decibels (dB(L)) for more than 5% of the total number of blasts carried out on the premises within the 12 months annual reporting period; and b) 120 dB(L) at any time.
Ground vibration criteria:	a) exceed 5 millimetres/second (mm/s) for more than 5% of the total number of blasts carried out on the premises within the 12 months annual reporting period; and b) 10mm/s at any time.
Sampled:	01/09/2022 – 30/09/2022

Table 5. Blast Overpressure Monitoring Summary

Date	Time	Ground Vibration (mm/s)			Overpressure (dBL)		
		BLK	MRE	SCH	BLK	MRE	SCH
02/09/22	3:06:36 PM	0.17	1.14	0.06	98.4	108.3	97.7
07/09/22	11:29:11 AM	0.23	0.60	0.07	98.90	108.30	100.00
08/09/22	1:33:52 PM	0.29	1.32	0.06	97.70	100.60	88.40
08/09/22	1:35:05 PM	0.13	1.03	0.04	94.10	104.30	95.20
10/09/22	3:02:59 PM	0.10	1.25	0.07	110.60	111.60	99.50
12/09/22	2:56:51 PM	0.31	2.29	0.14	97.90	104.00	94.80
15/09/22	3:54:49 PM	0.08	0.44	0.05	89.40	101.00	90.10
17/09/22	3:23:46 PM	0.24	2.61	0.15	95.20	109.40	106.20
20/09/22	10:28:55 AM	0.09	1.44	0.05	93.40	101.60	89.20
26/09/22	10:36:39 AM	0.19	1.81	0.08	94.90	99.80	91.70
28/09/22	10:40:38 AM	0.19	1.56	0.09	106.50	102.90	100.00
30/09/22	2:40:24 PM	0.13	1.35	0.17	118.60	105.40	110.70

Appendix A

PM10 Monitoring Locations



PRJ31060_BengallaMineNSW_50cm_19102017_gda84mgas6_ortho_full-area



BENGALLA MINE
PM10 Monitoring Locations

Appendix B

TSP Monitoring Locations



PRJ31060_BengallaMineNSW_50cm_19102017_gda94mgas56_ortho_full-area



BENGALLA MINE
TSP Monitoring Locations

Appendix C

Depositional Dust Monitoring Locations




PR31060_BengallaMineNSW_50cm_19102017_gd94mg956_ortho_full-area



BENGALLA MINE
 Depositional Dust Monitoring Locations

Appendix D

Noise and Blast Monitoring Locations



BENGALLA MINE

Bengalla Compliance Acoustic Monitoring Network

FIGURE 1

Lot	Lot No.	Lot Name
1	210	210
2	211	211
3	212	212
4	213	213
5	214	214
6	215	215
7	216	216
8	217	217
9	218	218
10	219	219
11	220	220
12	221	221
13	222	222
14	223	223
15	224	224
16	225	225
17	226	226
18	227	227
19	228	228
20	229	229
21	230	230
22	231	231
23	232	232
24	233	233
25	234	234
26	235	235
27	236	236
28	237	237
29	238	238
30	239	239
31	240	240
32	241	241
33	242	242
34	243	243
35	244	244
36	245	245
37	246	246
38	247	247
39	248	248
40	249	249
41	250	250
42	251	251
43	252	252
44	253	253
45	254	254
46	255	255
47	256	256
48	257	257
49	258	258
50	259	259
51	260	260
52	261	261
53	262	262
54	263	263
55	264	264
56	265	265
57	266	266
58	267	267
59	268	268
60	269	269
61	270	270
62	271	271
63	272	272
64	273	273
65	274	274
66	275	275
67	276	276
68	277	277
69	278	278
70	279	279
71	280	280
72	281	281
73	282	282
74	283	283
75	284	284
76	285	285
77	286	286
78	287	287
79	288	288
80	289	289
81	290	290
82	291	291
83	292	292
84	293	293
85	294	294
86	295	295
87	296	296
88	297	297
89	298	298
90	299	299
91	300	300
92	301	301
93	302	302
94	303	303
95	304	304
96	305	305
97	306	306
98	307	307
99	308	308
100	309	309

HOB0204.1.P13 142017 Bengalla Compliance Acoustic Monitoring Network - Audit/Review 09/2018