



ABN 32 053 909 470

T: +61 2 6542 9500 F: +61 2 6542 9599

bengalla.com.au

Bengalla Mine

Environment Protection Licence 6538 Monthly Monitoring Data Summary

December 2020





ABN 32 053 909 470

T: +61 2 6542 9500 F: +61 2 6542 9599

bengalla.com.au

Contents

1. 1	NTRODUCTION	3
2.	AIR QUALITY	4
3.	SURFACE WATER	5
4. I	NOISE	8
5.	BLASTING	10

Tables

Table 1. PM10 Monitoring Summary	5
Table 2. Noise – Bengalla Only LAeq (15 minute) Monitoring Summary	9
Table 3. Blast Overpressure Monitoring Summary	11
Table 4. Blast Vibration Monitoring Summary	11



ABN 32 053 909 470

T: +61 2 6542 9500 F: +61 2 6542 9599

bengalla.com.au

1. INTRODUCTION

BENGALLA

Environmental Protection Licence (EPL) holders are required under the *Protection of the Environment Operations Act 1997* to make publicly available their monitoring results for those parameters specified in the EPL. This document has been prepared to satisfy this requirement.

Bengalla Mining Company Pty Limited's (BMC) operations are conducted in accordance with EPL 6538. The licence details are as follows:

License Holder:	Bengalla Mining Company Pty Limited
Licence Number:	6538
Premises:	Bengalla Mine
	Bengalla Road via
	Muswellbrook NSW 2333
Access to Licence:	http://www.epa.nsw.gov.au/prpoeoapp/Detail.aspx?instid=6538&id=6538& option=licence&searchrange=licence⦥=POEO licence&prp=no&status=Issued
Monitoring Locations:	See main text and Appendix A

This document provides a summary of environmental monitoring data sampled as prescribed by EPL 6538 for December 2020 (Reporting Period). Monitoring data provided is as follows:

- Air quality, particulate matter less than 10 microns (PM₁₀);
- Surface water, including discharge mine water and effluent water;
- Noise; and
- Blast vibration and overpressure.





ABN 32 053 909 470

T: +61 2 6542 9500 F: +61 2 6542 9599

bengalla.com.au

2. AIR QUALITY

Under EPL 6538 BMC is required to continuously record the average PM_{10} concentration at EPA Monitoring Points 22, 23 and 24 at intervals of 10 minutes. As per Condition E1.1, BMC commenced monitoring at these EPA Monitoring Points on 31 August 2017.

 PM_{10} data for the Reporting Period is provided in **Table 1**.

2.1 Particulate Matter less than 10 Microns

Pollutant:	PM ₁₀
Unit of measure:	Micrograms per cubic metre (µg/m3)
Monitoring location:	See Table 1 and Appendix A.
Monitoring frequency required by licence:	10-minute intervals
Sampled:	01/12/2020 - 31/12/2020





ABN 32 053 909 470

T: +61 2 6542 9500 F: +61 2 6542 9599

bengalla.com.au

www.bengalla.com.au

Table 1. PM10 Monitoring Summary

Sai	mpling point	No. of samples required by licence	No. of samples collected and analysed	Minimum sample value	Maximum sample value	Monthly mean of sample
EPA22	Lumeah Dairy, Bengalla Road, Muswellbrook	4464	4015 ¹	0	184.6	10.2
EPA23	Wybong Road (East), Muswellbrook	4464	4456	0	222.5	12.9
EPA24	Wybong Road (West), Muswellbrook	4464	4455	0	78.9	10.1

(Table 1 represents total impact (ie incremental increase in concentration due to the development plus background concentrations due to other sources))

1. Due to a monitor programming error, EPA22 failed to record readings on the half hour commencing 15/12/2020 at 10:30am. This was rectified when discovered on 14/1/2021. All other 10 minute measurements were recorded.

3. SURFACE WATER

3.1 Discharge Monitoring

BMC participates in the Hunter River Salinity Trading Scheme (**HRSTS**). In accordance with EPL 6538, BMC maintains two monitoring locations to measure concentration, volume and mass of mine water discharges (see **Appendix B**).

3.1.1 Volume

Pollutant:	Mine water
Unit of measure:	Mega litres per day (ML/day)
Monitoring location:	EPA26 – Outlet pipe from 700 ML HRSTS storage dam.
Monitoring frequency required by licence:	Continuous during all discharge events.





ABN 32 053 909 470

T: +61 2 6542 9500 F: +61 2 6542 9599

bengalla.com.au

Volume/mass limit:	200 ML/day
Sampled:	Not applicable. During the Reporting Period, Bengalla did not discharge any mine water under the HRSTS.
3.1.2 Conductivity	
Pollutant:	Conductivity
Unit of measure:	Microsiemens per centimetre (µS/cm)
Monitoring location:	EPA26 – Outlet pipe from 700 ML HRSTS storage dam.
	EPA2 – Tributary monitoring point in Dry Creek downstream of EPA26.
Monitoring frequency required by licence:	Continuous during all discharge events (EPA26); Two times daily during discharge (EPA02).
Sampled:	Not applicable. During the Reporting Period, Bengalla did not discharge any mine water under the HRSTS.

3.1.3 Total suspended solids and pH	
Pollutants:	pH and Total Suspended Solids (TSS)
Unit of measure:	pH and Milligrams per litre (mg/L)
Monitoring location:	EPA26 – Outlet pipe from 700 ML HRSTS storage dam.
Monitoring frequency required by licence:	Daily during all discharge events
pH limit:	6.5 – 9.5 (100 th percentile) (Applies to EPA26 only)
TSS limit:	120 (100 th percentile) (Applies to EPA26 only)
Sampled:	Not applicable. During the Reporting Period, Bengalla did not discharge any mine water under the HRSTS.





ABN 32 053 909 470

T: +61 2 6542 9500 F: +61 2 6542 9599

bengalla.com.au

3.2 Effluent Quality Monitoring

Under EPL 6538 BMC is required to take quarterly grab samples from effluent quality monitoring point EPA25.

Pollutants:	Faecal Coliforms and pH
Unit of measure:	Colony Forming Units (CFU) per 100 millilitres (CFU/100mL) and pH
Monitoring location:	EPA25 – See Appendix B .
Monitoring frequency required by licence:	Quarterly

Sampled:

12 December 2020

Pollutant	Unit of measure	No. of samples required by licence	No. of samples taken and analysed	Sample Date	Sample Time	Measured value
Faecal Coliforms	CFU/100mL	1	1	01/12/2020	12:45 pm	<2
рН	pН	1	1	01/12/2020	12:45 pm	6.89





ABN 32 053 909 470

T: +61 2 6542 9500 F: +61 2 6542 9599

bengalla.com.au

4. NOISE

In accordance with EPL 6538, BMC undertakes compliance attended noise monitoring for 15minutes once per calendar month during the night period (10 pm to 7 am) at three locations representative of the nearest private receivers.

Noise monitoring data for the Reporting Period is provided in Table 5.

Pollutant:	Noise – Bengalla Only
Unit of measure:	LAeq (15 minute)
Monitoring locations:	See Table 2 and Appendix C.
Monitoring frequency required by licence:	Monthly
EPA7/AN01 limit:	35 dB(A)
EPA9/AN04 limit:	35 dB(A)
EPA8/AN03 limit:	40 dB(A)
Sampled:	24 December 2020





Bengalla Mining Company Pty Limited

	ABN 32 053 909 470	bengalla.com.au
OPE	Bengalla Road (Locked Mailbag 5) Muswellbrook NSW 2333 Australia	T: +61 2 6542 9500 F: +61 2 6542 9599

Table 2. Noise – Bengalla Only¹ LAeq (15 minute) Monitoring Summary

Sampling point	No. of samples required by licence	No. of samples taken and analysed	Sample Date	Sample Time	Measured value
EPA07/AN01	1	1	24/12/2020	00:41 – 00:56	29
EPA08/AN03	1	1	24/12/2020	01:17 – 01:32	32
EPA09/AN04	1	1	24/12/2020	01:46 - 02:01	IA

Note:

1. LAeq,15minute operational noise levels for Bengalla in the absence of all other noise sources.

IA - Inaudible. When there was no noise from the source of interest (Bengalla Mine) audible at the monitoring location.

Operator, for and on behalf of Bengalla Joint Venture, an unincorporated joint venture between: New Hope Bengalla Pty Ltd, Taipower Bengalla Pty Limited.

www.bengalla.com.au





ABN 32 053 909 470

T: +61 2 6542 9500 F: +61 2 6542 9599

bengalla.com.au

5. BLASTING

In accordance with EPL 6538, BMC maintains three blast monitors on private (non-mine owned) land to measure air-blast overpressure and ground vibration for all blast events undertaken at Bengalla.

Overpressure and ground vibration data for the Reporting Period is provided in Tables 3 and 4.

Pollutant:	Air blast overpressure & ground vibration peak particle velocity				
Unit of measure:	dB (Lin Peak) and millimetres per second (mm/s)				
Monitoring locations:	See Table 3, Table 4 and Appendix C.				
Monitoring frequency required by licence:	All blasts				
Overpressure limits:	 a) 115 linear decibels (dB(L)) for more than 5% of the total number of blasts carried out on the premises within the 12 months annual reporting period; and 				
	b) 120 dB(L) at any time				
Ground vibration limits:	 a) exceed 5 millimetres/second (mm/s) for more than 5% of the total number of blasts carried out on the premises within the 12 months annual reporting period; and b) 10 period is a second secon				
	b) 10mm/s at any time				
Sampled:	01/12/2020 – 31/12/2020				





Bengalla Mining Company Pty Limited

ABN 32 053 909 470	bengalla.com.au
Bengalla Road (Locked Mailbag 5) Muswellbrook NSW 2333 Australia	T: +61 2 6542 9500 F: +61 2 6542 9599

bengalla.com.au

Table 3. Blast Overpressure Monitoring Summary

Sampling point	Pollutant	Unit of measure	No. of samples required by licence	No. of samples collected and analysed	Minimum value	Maximum value	Mean of samples
BLK (EPA20)	Overpressure	dB(L)	All blast events	15	89.60	115.30	101.22
SCH (EPA19)	Overpressure	dB(L)	All blast events	15	80.40	99.30	92.33
MRE (EPA12)	Overpressure	dB(L)	All blast events	15	95.10	117.50	106.05

Table 4. Blast Vibration Monitoring Summary


Sampling point	Pollutant	Unit of measure	No. of samples required by licence	No. of samples collected and analysed	Minimum value	Maximum value	Mean of samples
BLK (EPA20)	Ground vibration	mm/s	All blast events	15	0.02	0.47	0.22
SCH (EPA19)	Ground vibration	mm/s	All blast events	15	0.02	0.17	0.08
MRE (EPA12)	Ground vibration	mm/s	All blast events	15	0.08	3.23	1.63

Operator, for and on behalf of Bengalla Joint Venture, an unincorporated joint venture between: New Hope Bengalla Pty Ltd, Taipower Bengalla Pty Limited.

www.bengalla.com.au

Appendix A

EPL 6538 Particulate Matter Monitoring Locations



EPL 6538 PM10 Monitoring Locations


Hansen Bailey

-

D will 7102 8085 Answell principally clauD is builed hough building and an employed the UKANS884

Appendix B

EPL 6538 Surface Water Monitoring Locations






EPL 6538 Effluent Quality Monitoring Location

PRJ32266 BengaliaMineNSW 50cm 25072018 gd994mm4866 onto full-area

Appendix C

EPL 6538 Noise and Blast Monitoring Locations



EPL 6538 Noise & Blast Monitoring Locations

Hansen Bailey